

X REVISED

JOB HAZARD ANALYSIS - Task Specific

NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CA	WESTERN HAZARD CATEGORY*	
Install Luminaries	Energy/WorkSite Haza	Energy/WorkSite Hazards	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Electricity/Working at H	Electricity/Working at Heights	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT	LOSS POTENTIAL RATING*	
Electrician	Moderate	Moderate	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specif	*refer to Stantec Specific Job Report	
safety glasses, safety footwear, <i>class zero</i> gloves, lock-out tag and Lock,	test meter, drill, ladder, gloves a	s required	Ken Gee
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURI	E
Assess Work Site	Slip, trip, fall from height	WP-41, Ladder safety training	
Remove luminaries from cardboard box	Cuts	gloves as required	
Install luminaries in ceiling grid	Fall from height, strain, lifting	Ladder safety training, materials handling training	
Pre-use inspection on drill	pinch, cut, twist	pre-use inspection	
Support luminaries	Fall from height, strain, lifting, noise	Ladder safety training, <i>materials handling training</i> , hearing protection	
Test wiring for electrical power	Shock	Lock-out tag-out, test meter, class zero gloves	
Install wiring	Fall from height	Ladder safety training	
Install lamps and lense	Fall from height	Ladder safety training	
Turn on electric circuit			