



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal of asbestos flex connections

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (Acmf)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Grade 1 safety footwear,safety glasses/goggles,half-face or full-face appropriate respiratory protection,tyvek coveralls,hearing protection(I.R.)

WESTERN HAZARD CATEGORY*

HAZARD TYPE*

LOSS POTENTIAL RATING*

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Post warning signs on all entries to the room	Cut,puncture	PPE,WHMIS,Clean/protect work area
Shut off,lock and tag the unit to be worked on	Struck against/by	Work by trained/licensed workers
HEPA vacuum on and about the flex connection	Pinch point,noise	
Place 6mil polyethylene below connection (if required)		
Use water and surfactant to saturate abestos cloth		
Using hand tools only , remove mechanical fasteners and remove flex connection		
Vacuum or wet wipe any loose material remaining		
Disposable coveralls shall be HEPA vacuumed or wet wiped		
All material for disposal shall be placed in an appropriate container and be double bagged or doublewrapped in 6mil plastic		
w		note: comply with Reg 278/05