

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure Dec 2, 2015		Time(s): 8:00	am - 3:00pm				
Building(s) #1 DENTAL SCIENCE BUILDING (DSB) #2 Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: Roof system C shutdown.							
Service to be #1 Fume Hoods #2 #2 #4 Description/Reason for Project:							
Exhaust system for 110-035 & 036 requires repair.							
Requester: Steve MacKay Date of Request: Nov 27, 2015							
Supervising Tradesperson:		Unit:					
rade Supervisor: Steve MacKay Unit: Motor Date:Nov 27, 201				Date:Nov 27, 2015			
Contractor:		Pho	ne # +1 (519) 451-4199				
Coordinator/Project Manager: Steve macKay	Pho	Phone # 88764 Date:1					
Reviewed by Trade Supervisor(s)/Shop(s) Affected:							
Name: WES Control	Date: Nov 30, 2015	Name:		Date:			
Signature/ Stamp:		Ctomps	REVIEWED / Wayne Drummond (ppdwad@uwo.ca) at	t 8:15 am, Nov 30, 2015			
Name:	Date:	Principal Occu	Principal Occupants:				
Signature/		Name:	Ext.	Date:			
Stamp:		Name:	Ext.	Date:			
Name:	Date:	Name:	Ext.	Date:			
Signature/		Name:	Ext.	Date:			
Stamp:		A	pproval to Proceed:	Date:			
Name:	Date:	APPROVED					
Signature/ Stamp:			By Dan Trudgeon (fminterr@uwo.ca) at 8:46 am, Dec 01, 2015				
Notes: Both Kevin Inchley & Bruce Arppe are	aware of the shutd	lown.					

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING DENTAL SCIENCE

SYSTEM	ROOM#	FAN	OUTLET	USE	NOTES
#	0400	LOCATION	LOCATION		
-025-	0128	C		Sterilizer Exhaust	
-026-	0115	<mark>C</mark> <u>C</u>	<mark>C</mark> C	Room Exhaust	CHECK FOR FAMI
<mark>-028-</mark>	0140B	-		Room Exhaust	CHECK FOR FAN!
-035-	2005	С	С	ELEPHANT TRUNKS PNL5P #3	
-036-	2005	С	С	ELEPHANT TRUNKS PNL5P #6	
-037-	2010B	С	С	DOUBLE Fume Cab PNL 5P #14	
-038-	2011	С	С	FUME CAB	PNL 5P #21
-039-	2011?	С	С	NOT SURE!	SHUTDOWN MAY6TH 2014.
-040-	2003	С	С	Fume Cab	
-042-	3003D	С	С	Fume Cab	
-043-	3003D	C	C	Room Ex.	Can't be isolated on roof control wires don't go to MCC.
-044-	3003	С	С	Fume Cab	
-045-	3004	С	С	Fume Cab	
-046-	3004	С	С	Fume Cab	
-047-	3004	С	С	Fume Cab	
-048-	3005A	C	C	Sterilizer Ex.	
-049-	3005B	С	С	Fume Cab	
-050-	3005,3006	C	C	Autoclave Ex.	See Note 3
-051-	2006	С	С	Fume Cab	OUT OF SERVICE
-052-	3006B	С	С	Fume Cab	
-061-	4001	C	C	Dissection Rm.	
-062-	4011	С	С	Fume Cab	
SYSTEM	ROOM#	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-063-	<mark>4012</mark>	C	C	Hood/spectrometer	
-064-	4014	С	С	Hood	
-065-	4015	С	С	Fume Cab	
-105- 504	0133	C	C	Operating Rm. Ex.	

Notes:

- 2- Hood was shown on building print, was not installed. Fan is on roof capped off.
- 3- Fume cabinet removed from 3006 system was connected to autoclave
- 4- Fume cabinet was removed from 3006 and connected to fume cabinet in room 2006
- 6- Door to be propped open when fan is shut down.

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN

ORANGE FILL – INDICATES CHANGES HAVE BEEN MADE, INFO MAY BE INCORRECT OR MISSING.

-039- FAN WAS STILL RUNNING. WE SHUT IT DOWN ON MAY 6^{TH} 2014. WAITING TO SEE IF ANYONE REPORTS ANYTHING OFF. MAY BE CAPPED IN CEILING. WILL UPDATE WHEN WE HEAR ANYTHING. - CV