JOB HAZARD ANALYSIS - Task Specific

Western

☐ NEW ☒ REVISED

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CATEGORY*	DATE:
Incinerator Cleaning	Eneregy/Worksite Hazards	June 27, 2007
DEPARTMENT	**HAZARD TYPE***	**WRITTEN BY:**
Facilities Management	Electricity/Slips/Trips/Falls	Iain Findlater
WESTERN JOB CLASSIFICATION*	**LOSS POTENTIAL RATING***	**REVIEWED BY:**
Power Plant Staff	Moderate	Rod Crichton
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	***refer to Stantec Specific Job Report**	**MGMT APPROVAL:**
Gloves, dusk mask, safety glasses/ goggles, safety footwear		

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Start scrubber ID fan	No Hazards	Refer to Incinerator Cleaning Procedure
Open ash door	Breathing in dust	Refer to Incinerator Cleanout Procedure to eliminate the discharge of ash into the workspace. Use proper lifting techniques, proper ventilation.
Increase ID fan speed to 85%	No Hazards	Refer to Incinerator Cleaning Procedure
De-ash	Back injury, dust	Refer to Incinerator Cleaning Procedure. PPE - dust mask. Proper lifting techniques