

REVISED

JOB HAZARD ANALYSIS - Task Specific

X NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CATEGORY*	DATE:
Emergency repair sprinkler system	WorkSite/ Ergonomic Hazards	June 29, 2006
DEPARTMENT	HAZARD TYPE*	WRITTEN BY:
CCPS	Sharp objects, struck by, working alone/weight	Steve Clemens
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RATING*	REVIEWED BY:
Fire Safety Staff	Moderate	Steve Clemens
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specific Job Report	MGMT APPROVAL:
grade 1 safety footwear		

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Disconnect drain/water supply, remove brackets/ supports/fasteners	Inadequate space, sharp	PPE, Proper lifting methods, assistance if
	material, projectile	possible/necessary/ use of lifting device
Lift/remove unit, fix/ repair location as required	Position, struck	Work by experienced trades only
	by/against, weight,	
	slip/fall, slippery material	
	working alone	