



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Pull Control Wire in Conduit

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves, asbestos mask and coveralls

WESTERN HAZARD CATEGORY*

Energy/WorkSite Hazards

HAZARD TYPE*

Electricity/Working at Heights

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Protect fish tape from contact with live electrical equipment	Shock, arc flash	Isolate live contact points
Feed fish into conduit	Ladder, position, asbestos	Ladder safety, asbestos procedures
Attach wire to fish tape	Ladder, position, strain	Ladder safety, use wire lubricant
Pull wire into conduit		
Remove wire from fish tape		
Rewind fish tape		