



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Traveling to and Visiting Work/Construction Sites

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

All FDE staff except for SJV and RL

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety shoes, hard hats, safety glasses (as per site requirements)

WESTERN HAZARD CATEGORY*

Work site hazards

HAZARD TYPE*

Slip/Trip/Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

December 19, 2006

WRITTEN BY:

Denis LeMay

REVIEWED BY:

MGMT APPROVAL:

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Walk across campus to work site	slips/trips/falls	walk carefully and watch for hazards
Enter work site: Laboratories, High Voltage Rooms, Construction	chemical/biological/ energy hazard	take lab safety for PPD
	falling objects and moving equipment	take electrical awareness
	falling off ladder	take construction awareness course and wear proper PPE (boots, hard hat and glasses)
		take ladder safety course