



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Changing Batteries

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Locksmith

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

safety glasses, gloves (when required)

**WESTERN HAZARD CATEGORY\***

Chemical Hazards

**HAZARD TYPE\***

Corrosive, Acute/Chronic Toxin

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ted Chelchowski

**REVIEWED BY:**

Structural Shop

**MGMT APPROVAL:**

Ted Chelchowski

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE       |
|------------------|-------------------|---------------------------|
| Remove Battery   | Chemical Contact  | Wear PPE                  |
| Cover - Remove   | Leaking Batteries | Clean up spilled solution |
| Batteries Change |                   | Call OHS if necessary     |
| Replaces cover   |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |
|                  |                   |                           |