



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Grinding, Die Grinding

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Locksmith

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, ear protection, safety gloves, faceshield (I.R.)

WESTERN HAZARD CATEGORY*

Physical/WorkSite/Equipment Hazards

HAZARD TYPE*

Noise/Projectiles/Machinery

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

1. Inspect grinder 2. Put on PPE 3. Grind metal	Flying sharp objects Noise Burns	Wear PPE including ear protection
4. Unplug grinder 5. Clean up mess		
* I.R. = if required		