

**x** REVISED

## JOB HAZARD ANALYSIS - Task Specific

NEW

		-	
WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CA	WESTERN HAZARD CATEGORY*   Energy Hazard   HAZARD TYPE*   Electricity   LOSS POTENTIAL RATING*   Moderate	
Hand Tools	Energy Hazard		
DEPARTMENT	HAZARD TYPE*		
Facilities Management	Electricity		
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT		
Locksmiths	Moderate		
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specific Job Report		MGMT APPROVAL:
Safety Glasses and Footwear			Ted Chelchowski
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE	
Use of hand tools	Electrocution	Inspect tools before use	
Scraping sanding, screwing and hammering	Cuts, shrapnel, eye injury	Wear PPE	
Maintain good safe tools		Dispose of defective tools	