



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Service Low Voltage Electronic Devices

WESTERN HAZARD CATEGORY*

Energy Hazard

DATE:

March 17, 2021

DEPARTMENT

Facilities Management

HAZARD TYPE*

Electricity

WRITTEN BY:

Ted Chelchowski

WESTERN JOB CLASSIFICATION*

Locksmith

LOSS POTENTIAL RATING*

Low

REVIEWED BY:

Structural Shop

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

*refer to Stantec Specific Job Report

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Removal and service and reinstallation of electronic locking mech.	Electrical shock	Wear PPE Read Instruction Manual so that work can be done without getting an electrical shock
		Example - remove batteries - lock out power source as per Lock-Out Tag-Out Policy WP-18 (see attached policy)