



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Servicing Doors (Hinging Mechanism)

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Locksmith

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves (I.R.), safety glasses/goggles (I.R.)

WESTERN HAZARD CATEGORY*

Ergonomic/WorkSite Hazards

HAZARD TYPE*

Weight/Pinch Points

LOSS POTENTIAL RATING*

Moderate/Low

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Removal of doors or hinges and reinstallation	Pinch point weight Slip - glass doors Tempered - exploding glass, projectile, sharp	Wear PPE Ask another staff member for help if necessary Follow Work Area Protection Policy WP-41 (see attached policy)
I.R. = if required		