



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Soldering

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Locksmith

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

WESTERN HAZARD CATEGORY*

WorkSite Hazard

HAZARD TYPE*

Fire/Explosion

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

April 5, 2006

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Ted Chelchowski

MGMT APPROVAL:

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Soldering various materials	Fire, burn chemical contact	Wear PPE If work could generate fire, follow Hot or Open Flame Work Procedure WP-43 (see attached policy)