



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Storage of Material

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Locksmith Service Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

If required: eye protection, ear protection, gloves. Safety footwear (always).

WESTERN HAZARD CATEGORY*

Ergonomic/WorkSite Hazards

HAZARD TYPE*

Weight/Working at Heights, Falling Objects

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Storage of material	Slip (ladder) weight sharp	Follow Work Area Protection Policy WP-41 (see attached policy) Wear PPE Use lifting & moving devices