



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Addition of sheet metal components to existing systems

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (ACMF)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

knee pads, hearing protection (I.R.), respiratory protection (I.R.), gloves, grade 1 safety footwear, safety glasses/goggles

**WESTERN HAZARD CATEGORY\***

WorkSite Hazards

**HAZARD TYPE\***

Working at Heights, Working alone

**LOSS POTENTIAL RATING\***

High

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up ladder/scaffold, protect work area	Position, fall, MMMF, sharp material, power/hand tools	PPE, proper ladder/scaffold use, assistance as required
Cut/drill as required, fasten/install/secure component, seal as necessary	Noise, working alone, struck against, slip/trip	Proper lifting techniques, verbal communication, clean work site
For installations such as takeoffs, dampers, fire dampers, splitter, etc		Work by licensed mechanic
*I.R. if required	*Required safe use of hand/power tools	*Note - comply with Reg 278/05 if ACM present