



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Alter/change vac. pump system

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (Plumber)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves, protective clothing, hearing protection (I.R.); grade 1 safety footwear, safety glasses/goggles. respiratory protection

WESTERN HAZARD CATEGORY*

Physical/ WorkSite/ Chemical hazards

HAZARD TYPE*

Noise/ Fire Explosion, Slips/Trips/Falls / Other Liquids

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

Plumbing/Fitting Shop

MGMT APPROVAL:

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Shut down vacuum, lock out,	Chemical contact	P.P.E., lockout/tag-out policy, hot work policy, WHMIS, fire blanket (I.R.) respiratory protection
Cut system as required; add new pipe, fittings	HBBF, sharp material	Proper ladder use (I.R.), work by trained/licensed tradesperson
Set up, solder in place,	Struck against, burn, fire	Inoculations to protect against infectious agents.
Support as required; protect work area,	Position, noise, inhalation	
Clean work site		
Safely dispose of waste		
I.R. If required. *If required safe use of power/hand tools.		*Note-comply with Reg 278 if ACM present