



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Service/maintenance/repair of ceiling mounted units

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (all)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Protective clothing, gloves, hearing protection (I.R.), grade 1 safety footwear, safety glasses/goggles

**WESTERN HAZARD CATEGORY\***

WorkSite/ Ergonomic Hazards

**HAZARD TYPE\***

Working at Heights, Working Alone/ Awkward Posture

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

Plumbing/Fitting Shop

**MGMT APPROVAL:**

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up ladder/scaffold	Position, sharp material,	PPE, proper lifting methods, lockout/tag-out policy, proper ladder use
Protect work area	Slip/trip/fall	Work by qualified/licensed trade
Remove ceiling tile/panels, perform work	Poor light, struck against, asbestos	Good portable light
Lock out equipment (I.R.) If live electrical trouble shooting is required follow safe electrical procedures	Shock,Arc Flash hazard	NFPA 70E guidelines
Remove equipment/material		
*Required safe use of power/hand tools		
	NOTE - Comply with Reg 278/05 If ACM present	