

x REVISED

JOB HAZARD ANALYSIS - Task Specific

NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD C	WESTERN HAZARD CATEGORY*	
Cut material-chop saw	Physical/ Chemical/ E	Physical/ Chemical/ Energy	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Noise/ Particulates/ H	Noise/ Particulates/ Heat	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RA	LOSS POTENTIAL RATING*	
Mechanical Trades (All)	Moderate		
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Spec	*refer to Stantec Specific Job Report	
Hearing protection, long sleeves, gloves, grade 1 safety footwear, safety gla	sses/goggles, respiratory protect	ction (I.R.)	Dan Gyetvai
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDUR	E
Check blade/guard	Projectile, noise	PPE, ensure unit safe, follow manufacturer's instructions	
Place/clamp material on base, cut as required	Cut, burn, skin contact, inhalation	Clear work area, clean up scrap/debris, lock down blade/guard when done	
Clean area		Work by qualified trade	
		Saw RPM must not exceed RPM printed on blade	
*Required safe use of hand/power tools			