

**x** REVISED

## **JOB HAZARD ANALYSIS - Task Specific**

NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CA	WESTERN HAZARD CATEGORY*	
Fabrication of sheet metal duct/fittings	Physical/ Worksite/ Eq	Physical/ Worksite/ Equipment Hazards	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Noise/ Pinch points, sh	Noise/ Pinch points, sharp objects/ Machinery	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT	LOSS POTENTIAL RATING*	
Mechanical Trades (ACMF)	Moderate	Moderate	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specif	*refer to Stantec Specific Job Report	
Hearing protection, protective clothing, gloves, grade 1 safety footwear, safety		Ken Hill	
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE	
Inspect equipment for damage and safe use	Position, sharp material, pinch point	PPE, follow manufacturer's instructions, proper lifting techniques, verbal communication	
Cut material as necessary	Power tools, noise, machinery	Proper lifting techniques, verbal communication	
Bend as required in 8' brake	Struck by, hand tools	Posted area	
Machine button lock or pittsburgh edge		Work by qualified tradesperson	
Put sections together			
*Required safe use of power/hand tools			