



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Hardware linkage installation

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (ACMF)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Hearing protection (I.R.), respiratory protection (I.R.), gloves (I.R.), grade 1 safety footwear, safety glasses/goggles

**WESTERN HAZARD CATEGORY\***

Worksite Hazards

**HAZARD TYPE\***

Struck by, pinch points, Noise

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

**SEQUENCE OF TASK**

**POTENTIAL HAZARDS**

**ACTION OR PROCEDURE**

Shut off equipment, Lock out/Tag out (I.R.)	Struck by/against, position	PPE, WHMIS, clean/protected work area
Drill, rivet, bolt, screw	Sharp material, pinch point, projectile, noise,	Proper ladder use, proper lifting techniques
Lubricate, adjust position, replace as required		Work by trained/licensed workers
*I.R. if required	*Required safe use of hand/power tools	*Note- comply with Reg 287/05 if ACM present