



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Locate, check, inspect fire dampers

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (ACMF)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Knee pads (I.R.), gloves (I.R.), grade 1 safety footwear, safety glasses/goggles, respiratory protection (I.R.)

WESTERN HAZARD CATEGORY*

Worksite/ Energy Hazards

HAZARD TYPE*

Working at Heights/ Electricity

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Locate duct/fire damper, shut down system (I.R.)	Position, fall,	PPE, safe ladder use, portable lighting
Remove access door to inspect fire damper	Poor light, man-made mineral fibre	Work by licensed mechanic
Check damper link installation		
Replace link if necessary		
Reinstall access door, turn on system (I.R.)		
		Note - Comply with Reg 278/05 if ACM present