



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Manual lifting of units, components

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (All)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Hard hat (I.R.), fall arrest equipment, gloves, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

Ergonomic/ WorkSite Hazards

HAZARD TYPE*

Manual Material Handling, Weight/ Working Alone

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up ladders/scaffold	Position, slip/fall	PPE, proper lifting method, pre-planning, keep clean work site
Restrict area, lift/move unit component to required location	Struck by, weight, sharp material	Verbal communication
	Working alone	Work/direction by trained tradesperson
I.R. if required	Note - Comply with Reg 278/05 if ACM present	*Required safe use of power/hand tools