



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Oxy-acetylene cutting

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (All)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Protective clothing, respiratory protection (I.R.), gloves, grade 1 safety footwear, safety glasses/goggles, face shield

**WESTERN HAZARD CATEGORY\***

Worksite Hazards

**HAZARD TYPE\***

Sharp Objects, Struck by, Slips/Trips/Falls, Pinch Point, Working alone

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Check equipment, test for material finish (I.R.), secure cylinders	Position, sharp material, burn struck by	PPE, test of material finish (I.R.), fire blankets, ventilation, fire watch
Protect work area, cut material, clean work site, dispose of material as required (2nd worker I.R.)	Slip/trip, pinch point, chemical exposure,	Hot work policy, barriers/ curtains, etc., verbal communication, fire extinguisher on site
Notify Work Control Centre	Working alone, fire	On site work by qualified tradesmen
I.R. if required		