



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal of fume cabinet/lab exhaust

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (acmf)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Respiratory protection (I.R.), grade 1 safety footwear, safety glasses/goggles, protective clothing, gloves

WESTERN HAZARD CATEGORY*

Chemical/ WorkSite hazards

HAZARD TYPE*

All chemicals/ Pinch points, sharp objects

LOSS POTENTIAL RATING*

Low

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Shut off Cabinet, Lock out/Tag out (I.R.)	Chemical contact, Inhalation, cuts.	PPE., proper ladder/scaffold use. Lockout/Tagout
Check system for corrosion/chemical leakage, test if required	Struck against, fall, trip	Co-worker assistance is required. lifting device (I.R.), maintain clean work site, dispose of material as required, dispose of protective clothing or wash separately.
Ensure safe work site, protect contents	Poor lighting	Work by informed licensed trade only.
Set up ladder/ scaffold	Position, weight, working alone	
Break joints, remove carefully		
Clean up area		
*Comply with Reg 278/05 IF ACM present		*I.R. safe use of power/hand tools