



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal/disposal of scrap material

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (All)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Protective clothing, gloves, respiratory protection (I.R.), grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

WorkSite/ Ergonomic Hazards

HAZARD TYPE*

Working alone, noise, slips/trips/falls, sharp objects / Awkward posture

LOSS POTENTIAL RATING*

High/ Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

Plumbing/Fitting Shop

MGMT APPROVAL:

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Lift/carry/transport scrap to truck, load onto truck	Weight, sharp material, struck by/against, strains	PPE, proper lifting methods, caution moving scrap, assistance as needed
Transport to disposal site	Projectile, noise, position	Keep work site clean as possible
Unload scrap	Trip/fall	Verbal communication
Place as required.	Working alone	Work by experienced trades.
	Vehicle accident	