



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal/installation of HVAC venting components

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (acmf)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Respiratory protection (I.R.), gloves, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

WorkSite/ Physical hazards

HAZARD TYPE*

Traffic, Falling Objects/ Noise

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

May 12, 2006

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up ladder or scaffold/ manlift	Fall, sharp materials, hand/power tools	PPE, inform occupants, proper ladder use
Protect work area, remove/install as required, dismantle/remove equipment	Traffic, noise, falling objects, position, trip	signs/barriers, proper lifting techniques, clean work area, manlift policy
		Work by trained/licensed worker
This is when working at/below ceiling (troffers, difusers, etc.)		
*I.R. if required	Note - Comply to Reg 278/05 if ACM present	*Required safe use of power/hand tools