



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal of sheet metal components

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (ACMF)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Hard hat (I.R.), hearing protection, respiratory protection (I.R.), gloves, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

WorkSite/ Ergonomic Hazards

HAZARD TYPE*

Working alone, slips/trips/falls, sharp objects, awkward posture

LOSS POTENTIAL RATING*

High/ Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE |
|--|---|--|
| Set up ladder/scaffold/manlift | Position, fall, struck by, slip/trip | PPE, post/protect site, safe ladder/scaffold/manlift use |
| Protect work area, cut/remove support, break joints, drop/carry to floor | Weight, projectile, hand tools, sharp material, | Verbal communication, proper lifting techniques |
| Clean up material, dispose | Particulate | Work by trained, licensed workers |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| *I.R. if required | Note - Comply with Reg 278/05 if ACM present | *Required safe use of power/hand tools |