



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Service repair of A/C equipment on top of walk-in equipment

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (refrigeration)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Respiratory protection (I.R.), grade 1 safety footwear, safety glasses, knee pads.

WESTERN HAZARD CATEGORY*

WorkSite/ Ergonomic Hazards

HAZARD TYPE*

Working alone/ Awkward Posture

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up ladder	Kneel on	PPE
Remove ceiling tile	Struck against, position.	Co-worker assistance if required
Climb on top of unit	Working alone	Proper ladder use.
Perform work as required	Inhalation	Good portable light
	Fall, poor light	Work by licensed trades.
Lock out equipment (I.R.) If live electrical trouble shooting is required follow safe electrical procedures	Shock,Arc Flash hazard	Follow NFPA 70E guidelines
I.R- If Required		