



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Repair seized variable vanes

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (acmf)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves, hearing protection, respiratory protection, appropriate clothing, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

WorkSite/ Ergonomic Hazards

HAZARD TYPE*

Working alone, slips/trips/falls, sharp objects / Weight, Awkward position

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Shut off/lock off unit, disconnect operator, remove impeller access	Sharp material	PPE, good portable light
Free up linkage /blades/knuckles with hand/power tools or lubricant	Poor light, burn, struck against	Lockout/tag-out policy, WHMIS, proper lifting methods, clean work site, assistance if require
Clean up/dispose of debris	Inhalation	Work by experienced trade *
	Trip/fall, weight, position, noise	
	Working alone	
* Required safe use: power /hand tools		