



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Use of hand held-power tools

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (All)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves, hearing protection (I.R.), respiratory protection (I.R.), required clothing, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

Equipment Hazards

HAZARD TYPE*

Power tools

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Inspect tool/cord, to ensure safe/take out of service (I.R.)	Projectile, burn, sharp material	PPE, anti - vibe gloves (I.R.)
Read operating instructions (I.R.)	Struck by/against, vibration, repetitive strain	Protect from damage, use Ground Fault Circuit Interrupter (I.R.)
Replace attachments (I.R.)	Noise, position	If unsafe, tag-out/ ensure repair or replacement
Grip firmly for use		Use by manufacturer's instructions
Maintain in good condition		
Reference for		
*Drill, sawzall, jigsaw, die grinder, mini-grinder, etc.	**I.R. if required	