



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Battery Replacement On Floor Machine

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Motor Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety boots, glasses, full face visor, rubber gloves, rubber apron

WESTERN HAZARD CATEGORY*

Ergonomic Hazards

HAZARD TYPE*

Weight

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

T. McLennan

REVIEWED BY:

Motor Shop

MGMT APPROVAL:

Mike Howard

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Clean battery surfaces if necessary (water baking soda)	Acid burns	Use of proper battery lifter.
Remove jumpers (... first)	Lift/bend	