



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Changing Fuses

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Motor Mechanic, Service Mechanic

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety boots, safety glasses, rubber gloves

**WESTERN HAZARD CATEGORY\***

Energy Hazard

**HAZARD TYPE\***

Electricity

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

T. McLennan

**REVIEWED BY:**

Motor Shop

**MGMT APPROVAL:**

Mike Howard

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Switch off breaker/disconnect	Electrical Shock	Ensure proper lighting.
Check for voltage	Position	Practice electrical safety
Pull fuses		Leave area clean/debris free
Investigate why fuses blown		Two qualified people if possible
Replace fuses		
Switch on		