



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Fan Coil Units Containing Mould, Rodents, Asbestos

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Service Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety boots, safety glasses, rubber gloves, dust mask

WESTERN HAZARD CATEGORY*

Chemical/Biological/WorkSite hazards

HAZARD TYPE*

Particulates/Antigens, Mould/Animals

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

T. McLennan

REVIEWED BY:

Motor Shop

MGMT APPROVAL:

Mike Howard

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Remove cover	Asbestos exposure	Use of proper disinfectant.
Remove asbestos		Asbestos type 2 removal
Remove mould (disinfect)	Reaction to mould/mice	Proper disposal to mice
Clean/lube/check motor		Leave area clean/debris free
Check/replace filter		
Clean coil		
Replace cover		