



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Lab. Under Bench Fan Coil Units

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Motor Mechanic, Service Mechanic

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety boots/ shoes, safety glasses, knee pads

**WESTERN HAZARD CATEGORY\***

WorkSite/Chemical Hazards

**HAZARD TYPE\***

Protruding/Sharp Objects/All Chemical

**LOSS POTENTIAL RATING\***

Low

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

T. McLennan

**REVIEWED BY:**

Motor Shop

**MGMT APPROVAL:**

Mike Howard

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Ensure lab is safe for entry	Position	Lab safety procedure
Check for broken glass, spilled chemicals etc.	Sharp materials Chemical contact Broken glass	Leave area clean/debris free
Remove cover		
Clean/lube/check motor		
Check/replace filter		
Clean coil		
Replace cover		