



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Automatic Transfer Switch Operation

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Emergency System Generator Mechanic/Motor Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, electrical gloves, safety shoes, arc flash protection

WESTERN HAZARD CATEGORY*

Energy/WorkSite/Chemical Hazards

HAZARD TYPE*

Electricity/Struck By Moving Object/Irritant

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

T. McLennan

REVIEWED BY:

Motor Shop

MGMT APPROVAL:

Mike Howard

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Visual inspection of inside of transfer switch	Short circuit fault	Practice electrical awareness procedures.
Ensure door is shut and fastened	Flash burn	Body position should always be to the side of panel while operating
Initiate operation while standing to the side	Struck by parts	
	Bruising	
	Inhalation of chemicals	