



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Drywall Tape & Mud

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Painter

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety glasses, safety footwear, gloves, respiratory protection

**WESTERN HAZARD CATEGORY\***

Ergonomic/WorkSite/Chemical Hazards

**HAZARD TYPE\***

Repetitive Strain/Slips/Trips/Falls, Working at Heights/Particulates

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ted Chelchowski

**REVIEWED BY:**

Structural Shop

**MGMT APPROVAL:**

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Safe Ladder Policy	Cuts	Safety Ladder Policy - see pages attached
Keep work area clear to work	Repetitive strain wrist and shoulder	limit repetitive tasks
Use hand cream to moisten hands after to prevent dermititis, etc.	Skin problems (hands)	particulate filter when sanding
When mudding and/or sanding large areas take rests; if possible, change type of work specially when the work is overhead	Inhaling sanding dust	wear PPE
Clean filler spills	Slips/falls	keep work area clean