



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Epoxy Painting

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves, personal protective equipment - Properly trained fitted Respirators with Proper filters

WESTERN HAZARD CATEGORY*

Chemical/ WorkSite hazards

HAZARD TYPE*

Irritant/ Slips.Trips.Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE |
|--|-------------------|--|
| Inspect work site | Dizziness | Clear work area |
| Seal off work area | Falls | Proper PPE |
| Install negative air system if necessary | Paint splatter | Keep work area well ventilated |
| Put on PPE (ie. respirator) | Strains | Put up proper barriers to warn occupants |
| Paint area | Dust | Use gloves |
| Keep area sealed off until dry | | Maintain ventilation until area dry |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |