

**x** REVISED

## JOB HAZARD ANALYSIS - Task Specific

NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD C	WESTERN HAZARD CATEGORY*	
Paint Shakers	Chemical/Equipment	Chemical/Equipment Hazards	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Other Liquids/Machine	Other Liquids/Machinery	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RA	LOSS POTENTIAL RATING*	
Painter	Moderate	Moderate	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Speci	*refer to Stantec Specific Job Report	
Safety Glasses			Ted Chelchowski
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDUR	E
Place closed gal of paint can in shaker	Major spraying if can is loose in machine	Before starting shaker check for tightness on can of paint	
Tighten can in place with machine	Clothing getting vise caught in shaker	Wear PPE	
Turn machine on		Stay clear of shaker while in operation, but never leave machine unattended while operating	
Turn machine off			
Remove gal of paint by untightening vise			