



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Painting

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety Footwear (Glasses, Gloves, and Respirator when required).

WESTERN HAZARD CATEGORY*

Ergonomic/Worksite hazards

HAZARD TYPE*

Overloading/Slips/Trips/Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

When using oil base paint, area needs to be well vented	Oil base paints	Check material hazards re WHMIS and MSDS
Caution with paint thinners as per MSDS	Heavy objects	Proper PPE
Inspect work site	Slips/trips/falls, strains	
Select appropriate paints	Dust & paint in eyes	Respirator ½ face may be needed- organic vapour
Opening and closing paint cans		Proper ventilation
Brush and roller work		Use caution with paint thinners
Use ladder for cutting and repairs when needed		Clean/clear work site
		Assistance from co-worker if needed
		Try and change work tasks
Rag disposal	spontaneous combustion	dispose in approved rag container

df