



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Respirators

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Mask (receive mask fitting training, use proper filters for each specific job)

WESTERN HAZARD CATEGORY*

Chemical Hazard

HAZARD TYPE*

Particulates

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Use mask when applicable to job - ex. sanding, using oil base paints, paint thinners, sealers, epoxy paints	Breathing	Use proper respirators for each job with appropriate filters
Dust masks	Spray	Take training as given by Western Health & Safety
Full face masks	Skin burns	Wear PPE
Pressure test masks before each use		Keep work area well vented