

JOB HAZARD ANALYSIS - Task Specific



Western

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Shop Spray Booth

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Respirators, Gloves, Safety Glasses and Footwear

WESTERN HAZARD CATEGORY*

Energy/Chemical Hazards

HAZARD TYPE*

Compressed Air/Irritant

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Turn on spray booth	Pressure hoses blowing apart	Before turning on power or pumps, check all hose connections
Prepare paint gun and connect to air supply	Trip hazards with hose	Keep area clean
Turn on air pressure to gun and set to desired pressure	Paint sprays	Wear PPE - have respirators properly fitted
Turn on lights		Be aware of object that being painted - not to fall over
		Keep all parts of booth clean of over spray
Paint object	Injection wounds	Keep body parts clear of tip
Load gun with cleaning solutions	Inhalation hazard	Keep respirator on during cleaning
Clean gun		
Shut off air pressure and empty gun		
Shut off spray booth		
Shut off lights		