



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Spinners

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Painter

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety Glasses

**WESTERN HAZARD CATEGORY\***

WorkSite/Chemical Hazards

**HAZARD TYPE\***

Pinch Points/Corrosive

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ted Chelchowski

**REVIEWED BY:**

Structural Shop

**MGMT APPROVAL:**

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Attach paint brush or roller to spinner	Spraying	Wear PPE
Place inside proper container	Fingers pinched	Use only proper containers supplied by shop
Spin until dry		Place containers in proper storage areas on shop
Store container in proper area		
maintain air ventilation while spinning	inhalation hazard	do not lean over spin bucket when spinning
dispose of broken handles	cuts	keep equipment maintained