



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Chillers - End Cap Removal

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Power Plant Staff

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Gloves, safety footwear

WESTERN HAZARD CATEGORY*

Energy/WorkSite hazards

HAZARD TYPE*

Electricity/Slips/Trips/Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

January 2, 2006

WRITTEN BY:

Iain Findlater

REVIEWED BY:

Rod Chrichton

MGMT APPROVAL:

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE |
|--|---|--|
| Lock-out energy sources | Slips, trips and falls | Refer to PPDs Lock-out/ Tag-out Procedure/ training to remove chance of discharging water under pressure or unintentional start up of equipment. |
| Identify and verify load restrictions on lifting points and lifting devices | Pinch points, slips/trips, falls | Refer to Lifting Device Procedure/Training to match load to correct lifting device |
| Set up lifting equipment | Pinch points, slips/trips, falls, back injury | Follow manufacturer's instructions, proper lifting techniques |
| Remove and store end caps | Pinch points, slips/trips, falls, back injury | Refer to Lifting Device Procedure/Housekeeping/ Training to keep work area clean and free of tripping hazards |
| To complete job - please reverse sequence of job steps and recommended actions | | |
| | | |
| | | |
| | | |

| | | |
|--|--|--|
| | | |
| | | |
| | | |
| | | |