



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

PRV Station Maintenance  
West Valley Mechanical Room, Ground Floor

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety glasses, hard hat, heat protective gloves, wrenches and other tools

**WESTERN HAZARD CATEGORY\***

Energy/Ergonomic Hazards

**HAZARD TYPE\***

Steam/Awkward Posture

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

December 14, 2006

**WRITTEN BY:**

Joe Reaume  
Mike Herman

**REVIEWED BY:**

**MGMT APPROVAL:**

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Isolate, lock-out & tag-out main steam supply to PRV Station	Surface burns due to contact with steam equipment	Refer to Lock-Out/Tag-Out Procedure and training to eliminate discharge of steam from vent
Walk between and around equipment to gain access		
Install lifting devices		
Remove and replace PRV or isolation valves	Ergonomical due to congestion and location	Refer to Lifting Device Procedure and training
Exit work space		
Remove and clean up tools		
Remove locks and tags		
Restore steam supply	Bumps, bruises	
	Falls	
