



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

PRV Station Operations
West Valley Mechanical Room, Ground Floor

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, hard hat, heat protective gloves, wrench

WESTERN HAZARD CATEGORY*

Energy/Ergonomic Hazards

HAZARD TYPE*

Steam/Awkward Posture

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

December 14, 2006

WRITTEN BY:

Joe Reaume
Mike Herman

REVIEWED BY:

Rod Crichton

MGMT APPROVAL:

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Steam supply to PRV Station remains in service	Burns - severe due to possible exposure to live steam	Job preplanning, wear appropriate PPE
Walk between 2 safety relief valves to gain access to PRV Station	Burns, bruises	Keep work area clear to minimize trips/falls in an already congested work space
	Surface burns due to contact with steam	Wear heat protective clothing
	Falls	
	Ergonomical de to congestion and location of equipment	
