

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

| Date of Interruption/Closure June 12, 201 | 15 | Time(s): | ime(s): 7:00am - 4:30pm | | | |
|--|-------------------|----------------------|--|------|--------------------|--|
| Building(s) #1 DENTAL SCIENCES BUILDING (DSB) #2 Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: | | | | | | |
| Areas served by Fans 101-104. See attached HVAC drawings. | | | | | | |
| Service to be #1 Chilled Water Feed #2 Fan 101-104 | | | | | | |
| interrupted: "" #2 Interrupted | | | | | | |
| #3 #4 Description/Reason for Project: | | | | | | |
| Steamfitters - Remove/replace steam coil on Fan 101. Shutdown of Fan 101 required which also requires 102, 103 & 104 offline, supply and return air. Rooms will be warmer and have less airflow than normal. ITS - Installing data cables to 0145 & 0139B. See attached print for affected areas. | | | | | | |
| Requester: Fernando Rascao / Dan Blumas Date of Request: May 28, 2015 | | | | | | |
| Supervising Tradesperson: Fernando Rascao Unit: Steamfitting Shop | | | | | | |
| Trade Supervisor: Dan Gyetvai Unit: Plumbing / Steamfitting Shop Date:May 28, 2015 | | | | | te:May 28, 2015 | |
| Contractor: Phone # | | | | | | |
| Coordinator/Project Manager: Phone # Date: | | | | | | |
| Reviewed by Trade Supervisor(s)/Shop(s) Affected: | | | | | | |
| Name: Plumber / Fitter Shop | Date: May 28, 201 | Name: | WES Control | | Date: May 28, 2015 | |
| Signature/ Stamp: | * | Signature/ Stamp: | INLVILVED | | | |
| Name: Electrical / Mechanical | Date: | Principal O | Principal Occupants: | | | |
| Signature/ H. Marcha | | Name: | | Ext. | Date: | |
| Stamp: Mex (24) | | Name: | | Ext. | Date: | |
| Name: | Date: | Name: | | Ext. | Date: | |
| Signature/ | | Name: | | Ext. | Date: | |
| Stamp: | | | Approval to Proceed: | | Date: | |
| Name: | Date: | APPR | APPROVED | | | |
| Signature/ Stamp: | | | By Dan Trudgeon (fminterr@uwo.ca) at 2:33 pm, May 29, 2015 | | | |
| Notes: Motor Shop work order # 530691. | | | | | | |