

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

					<u> </u>	
Date of Interruption/Closure March 27 - 30		Time(s): 7	:30 am- 4:00 pm dai	ly		
Building(s) #1 Pental Science Building (DSB) #2 Health Sc Addition (HSA) Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: Dental Sciences Building - equipment with hazardous exhausts to roof B C D E F G H & K Health Sciences Addition - All fume hoods See attached Sheet for affected hoods.						
Service to be #1 Hazardous Exhaust #2 #4 Description/Reason for Project: Continuation of mechanical work on roof B associated with the 6th floor lab project.						
Requester: Modern Niagara Mechanical			Date of Request:	Mar 15, 2	017	
Supervising Tradesperson: Trade Manager:						
Contractor: SEM Construction (Larry Northover) Coordinator/Project Manager:			Phone # +1 (151) 969-17	59	Date:	
Reviewed by Trade Manager(s)/Shop(s) Affected:						
Name: Electrical / Mechanical Shop	Date:	Name:	WES Control		Date:	
Signature/ Stamp: APPROVED By spepper (spepper@uwo.ca) at 11:36 am,	Mar 16, 2017	Signature/ Stamp:	REVIEWED By Wayne Drummond (ppdw	ad@uwo.ca) a	nt 1:43 pm, Mar 21, 2017	
Name:	Date:	Principal C	Occupants:			
Signature/		Name:		Ext.	Date:	
Stamp:		Name:		Ext.	Date:	
Name:	Date:	Name:		Ext.	Date:	
Signature/ Stamp:		, ruine.	Approval to Proceed:		Date:	
Name:						
ignature/ tamp: By Dan Trudgeon (dtrudgeo@uwo.ca) at 7:18 am, Mar 22, 2017					18 am, Mar 22, 2017	
Notes: Motor shop work order 603299						

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING DENTAL SCIENCE

SYSTEM #	ROOM#	FAN LOCATION	OUTLET	USE	NOTES
110- 001-500		6000	Wall of roof K	W.R. Exhaust	Louvre above K
-002-	003	003	Wall	Mech. Rm. Ex.	
-003-	4028 A&B	K	К	Room Exhaust	1 ½" acetone exhaust
-004-	Elev. Mach Rm.	Roof G	Roof G	Room Exhaust	
-005-	<mark>6000</mark>	<mark>6000</mark>	Wall of roof k	Mech. Rm. Ex.	Louvre Above K
-006-	5006	K	K	Fume Cabinet	
-007-	5006	K	K	Fume Cabinet	
-800-	5005	K	K	Fume Cabinet	
-009-	5005	K	K	Fume Cabinet	
-012-	5000-I	K	K	Room Exhaust	CAN NOT ACCESS
-013-	5000-H *CHECK NOTE?	K	K	Room Exhaust	CAN NOT ACCESS ROOM
-014-	4035A	K	К	Fume Cabinet	Radio Isotope – stack
-015-	0064,0068,0074,0078	M	M	Room Exhaust	????
-016-	5000 A	<mark>6000</mark>	Wall of Roof K	Shower Exhaust	Louvre above K
-018-	4030 – 4032	Top of stair 6	Wall of roof E	Room Exhaust	Louvre above E
-019-	4032	Top of stair 6	Wall of roof E	Fume Cabinet	Louvre above E
-020-	0010C	0012	Wall	Room Exhaust	
-023-	0025	К	K	Fume Cabinet	
-025-	0128	C	C	Sterilizer Exhaust	
-026-	<mark>0115</mark>	C	C	Room Exhaust	
-027-	0033,0034	L	L	3 Fume Cabinets	Installed 2008
-028-	0140B	C	C	Room Exhaust	CHECK FOR FAN!
-029-	0142E	<u> </u>		2 Hoods	????
-030-	0142X	K	K	Autoclave Ex.	still not in use – may 08 LOCKED

					OFF 2013
SYSTEM	ROOM #	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-031- A&B	COLLECTOR FAN ON RC	OOF M – DSB N	EW ADDITION		
-032-	1008B	K	К	Hood	Switch Rm. 1008D
-033-	1008B	K	К	Hood	
-034-	1018	K	K	Dryer Ex.	
-035-	2005	С	С	ELEPHANT TRUNKS PNL5P #3	
-036-	2005	С	С	ELEPHANT TRUNKS PNL5P #6	
-037-	2010B	С	С	DOUBLE Fume Cab PNL 5P #14	
-038-	2011	С	С	FUME CAB	PNL 5P #21
-039-	2011?	С	С	NOT SURE!	SHUTDOWN MAY6TH 2014.
-040-	2003	С	С	Fume Cab	
-042-	3003D	С	С	Fume Cab	
-043-	3003D	C	C	Room Ex.	Can't be isolated on roof control wires don't go to MCC.
-044-	3003	С	С	Fume Cab	
-045-	3004	С	С	Fume Cab	
-046-	3004	С	С	Fume Cab	
-047-	3004	С	С	Fume Cab	
-048-	3005A	C	C	Sterilizer Ex.	
-049-	3005B	C	C	Fume Cab	
<u>-050-</u>	3005,3006	<u> </u>	C	Autoclave Ex.	See Note 3
-051- -052-	2006 2006P	С	С	Fume Cab Fume Cab	OUT OF SERVICE
-054-	3006B 3013	C Top of stair 6	Wall of roof E	Fume Cab	Louvre Above E
-055-	2019	K	K	Fume Cab	6 TH FLOOR PANEL ED1H #29&31
-056-	3013B	K	K	Sterilizer Ex.	
-058-	<mark>3023</mark>	K	K	Hood	See note 6
-059-	6015	В	В	Room Ex.	Sheep Fac. DON'T SHUT OFF
-060-	0142X/T CHECK STARTER NEXT TO AUTOCLAVE #29	Roof L	Roof L	Equip. Ex.	Serves autoclave #29
-061-	4001	C	C	Dissection Rm.	
-062-	4011	С	С	Fume Cab	

SYSTEM	ROOM #	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-063-	<mark>4012</mark>	C	C	Hood/spectrometer	
-064-	4014	С	С	Hood	
-065-	4015	С	С	Fume Cab	
-066-	4019	6000	Wall of roof K	Autoclave Ex.	Louvre above K
-067-	5014	K	K	Solvent Room	
-068-	5001	K	K	Fume Cab	
-069-	5001	K	К	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS
-070-	4030	Top of	Wall of	Fume Cab	
		stair 6	Roof E		
-071-	<mark>0013</mark>	0013	Wall	Elec. Vault Ex.	
-072-	0012	0012	<mark>Wall</mark>	Mech. Rm. Ex.	
-074-	5002A	K	K	LABELED ROOM EX	
				NON HAZARDOUS?	
-075-	5541,5573	В	B	W.R. Ex.	
-076-		0003	<mark>Wall</mark>	W.R. Ex.	
-078-	4010	С	С	Fume Cab	FC removed from
					rm 4009
-079-	6010A	B	B	Exhaust Hoo	Hepa Filtered
-080-	6004,6005,6006	B	B	Room Ex.	Hepa Filtered
-081-	6007,6008,6009,6011	B	B	Room Ex.	Hepa Filtered
-081-	0142	L	L	Old Box fan on roof L – switch tagged of in room0142	
<mark>-082-</mark>	6050	<mark>B</mark>	B	Room Ex.	Sheep Fac. DON'T TURN OFF
-083-	3031	К	К	Fume Cab	Radioisotope Unit
-084-	2010G ???	E	E	Fume Cab	
-085-	2010G ???	E	Е	Fume Cab	
-086	0015	L	L	Fume Cab	New in 2003
-090-	4020,4021	6000	Wall of Roof K	Operating Rm. Ex.	Louvre above K
-091-	<mark>7000</mark>	G	G	Mach. Rm. Ex.	
-092-	0019	L	L	Fume Cab	
-093-	0032,0032A,0032B	L	L	Room/Autoclave Ex.	Switch in Rm. 0032B

SYSTEM	ROOM #	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-094	0021	L	L	Fume Cab	
-095-	6035	В	В	Cage Washer Ex.	
-096-	4034	К	К	Fume Cab	Radio Isotope stack
-097-	5004	К	K	Fume Cab	Radio Isotope stack
-002- 501	6022	B	В	Incinerator Ex.	
-003- 501	6022	B	B	Incinerator Ex.	
-004- 501		<mark>B65</mark>	Side Louver	General Ex.	
-005- 501		B65	Side Louver	Mechanical Rm. Ex.	
-006- 501-		Roof M	Roof M	Washroom Ex.	
-007- 501	5000	K	К	1 Fume Cab 1 Fume Hood	
-105- 504	0133	C	C	Operating Rm. Ex.	
-106- 504	5000A	Top of Stair 6	Wall Roof E	Animal Isolation Rm.	Louver Above
110- 108-507	3025	K	K	Room Exhaust	
110- 115-504		7001	Wall of Roof B	Animal quarters	
110- 108-505	3013	<mark>6000</mark>	Wall of Roof K	Animal Room Exhaust	Louver Above
NO#		G-MSB	G-MSB	Cage Washer	
111- 095-500	DSB-6035	G-MSB	G-MSB	Cage Washer	

Notes:

2- Hood was shown on building print, was not installed. Fan is on roof capped off.

- 3- Fume cabinet removed from 3006 system was connected to autoclave
- 4- Fume cabinet was removed from 3006 and connected to fume cabinet in room 2006
- 6- Door to be propped open when fan is shut down.

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN

ORANGE FILL – INDICATES CHANGES HAVE BEEN MADE, INFO MAY BE INCORRECT OR MISSING.

-039- FAN WAS STILL RUNNING. WE SHUT IT DOWN ON MAY 6^{TH} 2014. WAITING TO SEE IF ANYONE REPORTS ANYTHING OFF. MAY BE CAPPED IN CEILING. WILL UPDATE WHEN WE HEAR ANYTHING. - CV

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED: 2013 / 04 / 30

BUILDING	HEALTH
	SCIENCE
	ADDITION

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
114-001-500		<mark>500</mark>	NORTH WALL	W.R. EXHAUST	FED FROM MCC
002	202	500	NORTH WALL	FUME CABINET	FED FROM MCC
003	216	500	NORTH WALL	FUME CABINET	FED FROM MCC
<mark>004</mark>	<mark>316</mark>	H500	NORTH WALL	ROOM EXHAUST	SEE NOTE 2
006	301F	С	С	FUME CABINET	FED FROM MCC NEEDS
					NEW DOOR STICKER!
007	408	С	С	FUM,E CABINET	FED FROM MCC
008	418	С	С	FUME CABINET	FED FROM MCC
009	418	С	С	HOOD	FED FROM MCC SEE NOTE 3
012	406	С	С	FUME CABINET	
013	415	С	С	FUME BENCH??	

NOTES:

- 2 FAN IS STILL RUNNING IN PENTHOUSE MECHANICAL ROOM. NO INTAKE CAN BE FOUND IN ROOM 316. WHERE IS THIS FAN DRAWING FROM???
- 3 APRIL 2^{ND} 2013, ASKED TO LOCK FAN OFF AS IT WAS NOT PROPER SETUP FOR LAB APPLICATION. COMMON LOCK #13 WAS USED AT MCC IN PENTHOUSE MECHANICAL ROOM. –CV & SP.