

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail

Print Form

Date of Interruption/Closure December 5 - 8, 2016		Time(s): 7	:30am - 4:00pm		
Building(s) #1 Dental Science Building (DSB) #2 Health Sc Addition (HSA) Affected: #3 #4 #4 Areas/Rooms Affected Alternate Route/Service: December 5th: DSB Roofs B, C, D, E, F, G, H, & K and all HSA fume hoods. December 6-8: DSB Roofs B, C, D, E, F, G, H.					
Service to be #1 Hazardous Exhaust #2 #3 #4 Description/Reason for Project: Ongoing installation of equipment for work associated in the 6th floor laboratory project.					
Requester: Modern Niagara Mechanical			Date of Request:	Nov 25, 20	16
Supervising Tradesperson:		Unit:			
Trade Manager:		Unit:			Date:
Contractor: SEM Construction (Larry Northover) Coordinator/Project Manager: Boris Pertout Phone # +1 (519) 691-7593 Phone # +1 (519) 521-2551 Date:Nov 28, 2016					
Reviewed by Trade Manager(s)/Shop(s) Affected: Name: Electrical / Mechanical Shop Date	e: Nov 29, 2016	Name:	WES Control		Date: Nov 29, 2016
Signature/ Stamp: APPROVED By Steve MacKay (smackay@uwo.ca) at 10		Signature/ Stamp:	REVIEWED By Wayne Drummond (ppdwad@	luwo.ca) at 9:24 an	
Name:	- 0	Principal C	Occupants:		
Signature/ Stamp:		Name:		Ext.	Date:
Date	<u>.</u>	Name:		Ext.	Date:
Name.	-	Name:		Ext.	Date:
Signature/ Stamp:			Approval to Proceed:		Date:
Name: Date Signature/ Stamp:	APPROVED By Dan Trudgeon (dtrudgeo@uwo.ca) at 3:47 pm, Nov 29, 2010			7 pm, Nov 29, 2016	

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING DENTAL SCIENCE

SYSTEM	ROOM #	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-003-	4028 A&B	K	K	Room Exhaust	1 ½" acetone exhaust
-006-	5006	K	K	Fume Cabinet	
-007-	5006	K	K	Fume Cabinet	
-008-	5005	K	K	Fume Cabinet	
-009-	5005	К	K	Fume Cabinet	
-014-	4035A	K	K	Fume Cabinet	Radio Isotope – stack
-019-	4032	Top of stair	Wall of roof E	Fume Cabinet	Louvre above E
		6			
-023-	0025	K	K	Fume Cabinet	
-032-	1008B	K	K	Hood	Switch Rm. 1008D
-033-	1008B	K	K	Hood	
-035-	2005	С	С	ELEPHANT TRUNKS	
				PNL5P #3	
-036-	2005	С	С	ELEPHANT TRUNKS	
				PNL5P #6	
-037-	2010B	С	С	DOUBLE Fume Cab	
				PNL 5P #14	
-038-	2011	С	С	FUME CAB	PNL 5P #21
-039-	2011?	С	С	NOT SURE!	SHUTDOWN MAY6TH
					2014.
-040-	2003	С	С	Fume Cab	
-042-	3003D	С	С	Fume Cab	
-044-	3003	С	С	Fume Cab	
-045-	3004	С	С	Fume Cab	
-046-	3004	С	С	Fume Cab	
-047-	3004	С	С	Fume Cab	
-049-	3005B	С	С	Fume Cab	
-051-	2006	С	С	Fume Cab	OUT OF SERVICE
-052-	3006B	С	С	Fume Cab	
-054-	3013	Top of stair	Wall of roof E	Fume Cab	Louvre Above E
		6			TU
-055-	2019	К	K	Fume Cab	6 TH FLOOR PANEL ED1H
					#29&31
-064-	4014	С	С	Hood	
-065-	4015	С	С	Fume Cab	

-067-	5014	K	K	Solvent Room	
-068-	5001	K	K	Fume Cab	
-069-	5001	K	К	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS
-070-	4030	Top of stair 6	Wall of Roof E	Fume Cab	
-074-	5002A	К	К	LABELED ROOM EX NON HAZARDOUS?	
-078-	4010	С	С	Fume Cab	FC removed from rm 4009
-083-	3031	K	K	Fume Cab	Radioisotope Unit
-084-	2010G ???	E	Е	Fume Cab	
-085-	2010G ???	E	E	Fume Cab	
-090-	4020,4021	6000	Wall of Roof K	Operating Rm. Ex.	Louvre above K
-095-	6035	В	В	Cage Washer Ex.	
-096-	4034	K	K	Fume Cab	Radio Isotope stack
-097-	5004	K	K	Fume Cab	Radio Isotope stack
-007- 501	5000	К	К	1 Fume Cab 1 Fume Hood	

Notes:

- 2- Hood was shown on building print, was not installed. Fan is on roof capped off.
- 3- Fume cabinet removed from 3006 system was connected to autoclave
- 4- Fume cabinet was removed from 3006 and connected to fume cabinet in room 2006
- 6- Door to be propped open when fan is shut down.

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN

ORANGE FILL - INDICATES CHANGES HAVE BEEN MADE, INFO MAY BE INCORRECT OR MISSING.

-039- FAN WAS STILL RUNNING. WE SHUT IT DOWN ON MAY 6^{TH} 2014. WAITING TO SEE IF ANYONE REPORTS ANYTHING OFF. MAY BE CAPPED IN CEILING. WILL UPDATE WHEN WE HEAR ANYTHING. - CV

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED: 2013 / 04 / 30

BUILDING	HEALTH		
	SCIENCE		
	ADDITION		

SYSTEM #	ROOM #	FAN	OUTLET	USE	NOTES
		LOCATION	LOCATION		
002	202	500	NORTH WALL	FUME CABINET	FED FROM MCC
003	216	500	NORTH WALL	FUME CABINET	FED FROM MCC
006	301F	С	С	FUME CABINET	FED FROM MCC NEEDS
					NEW DOOR STICKER!
007	408	С	С	FUM,E CABINET	FED FROM MCC
008	418	С	С	FUME CABINET	FED FROM MCC
009	418	С	С	HOOD	FED FROM MCC SEE NOTE 3
012	406	С	С	FUME CABINET	
013	415	С	С	FUME BENCH??	

NOTES:

- 2 FAN IS STILL RUNNING IN PENTHOUSE MECHANICAL ROOM. NO INTAKE CAN BE FOUND IN ROOM 316. WHERE IS THIS FAN DRAWING FROM???
- 3 APRIL 2ND 2013, ASKED TO LOCK FAN OFF AS IT WAS NOT PROPER SETUP FOR LAB APPLICATION. COMMON LOCK #13 WAS USED AT MCC IN PENTHOUSE MECHANICAL ROOM. –CV & SP.