



Notice of Service Interruption/Area Closure
Western University
Facilities Management
Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
 Print Form

Date of Interruption/Closure: Time(s):

Building(s) Affected: #1 #2
 #3 #4

Areas/Rooms Affected Alternate Route/Service:

Service to be interrupted: #1 #2
 #3 #4

Description/Reason for Project:

Requester: Date of Request:

Supervising Tradesperson: Unit:

Trade Supervisor: Unit: Date:

Contractor: Phone #

Coordinator/Project Manager: Phone # Date:

Reviewed by Trade Supervisor(s)/Shop(s) Affected:

Name: <input type="text" value="Electrical / Mechanical Shop"/>	Date: <input type="text" value="May 4, 2016"/>	Name: <input type="text" value="WES Control"/>	Date: <input type="text" value="May 4, 2016"/>
Signature/Stamp: APPROVED <i>By Steve MacKay (smackay@uwo.ca) at 10:19 am, May 04, 2016</i>		Signature/Stamp: REVIEWED <i>By Wayne Drummond (ppdwad@uwo.ca) at 9:58 am, May 04, 2016</i>	
Name: <input type="text"/>	Date: <input type="text"/>	Principal Occupants:	
Signature/Stamp: <input type="text"/>		Name: <input type="text"/>	Ext. <input type="text"/>
Name: <input type="text"/>	Date: <input type="text"/>	Name: <input type="text"/>	Date: <input type="text"/>
Signature/Stamp: <input type="text"/>		Name: <input type="text"/>	Ext. <input type="text"/>
Name: <input type="text"/>	Date: <input type="text"/>	Name: <input type="text"/>	Date: <input type="text"/>
Signature/Stamp: <input type="text"/>		Approval to Proceed: <input type="text"/>	
Name: <input type="text"/>	Date: <input type="text"/>	APPROVED <i>By Dan Trudgeon (dtrudgeo@uwo.ca) at 7:46 am, May 06, 2016</i>	
Signature/Stamp: <input type="text"/>			

Notes:

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING	DENTAL SCIENCE
----------	----------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
-003-	4028 A&B	K	K	Room Exhaust	1 ½" acetone exhaust
-006-	5006	K	K	Fume Cabinet	
-007-	5006	K	K	Fume Cabinet	
-008-	5005	K	K	Fume Cabinet	
-009-	5005	K	K	Fume Cabinet	
-014-	4035A	K	K	Fume Cabinet	Radio Isotope – stack
-019-	4032	Top of stair 6	Wall of roof E	Fume Cabinet	Louvre above E
-023-	0025	K	K	Fume Cabinet	
-032-	1008B	K	K	Hood	Switch Rm. 1008D
-033-	1008B	K	K	Hood	
-054-	3013	Top of stair 6	Wall of roof E	Fume Cab	Louvre Above E
-055-	2019	K	K	Fume Cab	6 TH FLOOR PANEL ED1H #29&31
-067-	5014	K	K	Solvent Room	
-068-	5001	K	K	Fume Cab	
-069-	5001	K	K	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS
-070-	4030	Top of stair 6	Wall of Roof E	Fume Cab	
-074-	5002A	K	K	LABELED ROOM EX NON HAZARDOUS?	
-083-	3031	K	K	Fume Cab	Radioisotope Unit
-084-	2010G ???	E	E	Fume Cab	
-085-	2010G ???	E	E	Fume Cab	
-090-	4020,4021	6000	Wall of Roof K	Operating Rm. Ex.	Louvre above K
-096-	4034	K	K	Fume Cab	Radio Isotope stack
-097-	5004	K	K	Fume Cab	Radio Isotope stack
-007-501	5000	K	K	1 Fume Cab 1 Fume Hood	

Notes:

2- Hood was shown on building print, was not installed. Fan is on roof capped off.

3- Fume cabinet removed from 3006 – system was connected to autoclave

4- Fume cabinet was removed from 3006 and connected to fume cabinet in room 2006

6- Door to be propped open when fan is shut down.

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN

ORANGE FILL – INDICATES CHANGES HAVE BEEN MADE, INFO MAY BE INCORRECT OR MISSING.

-039- FAN WAS STILL RUNNING. WE SHUT IT DOWN ON MAY 6TH 2014. WAITING TO SEE IF ANYONE REPORTS ANYTHING OFF. MAY BE CAPPED IN CEILING. WILL UPDATE WHEN WE HEAR ANYTHING. - CV