

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure May 24, 2016 Time(s): 8:00 am - 3:00 pm									
Building(s) #1 DENTAL SCIENCE BUILDING (DSB) Roofs K & L #2 #4 Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: Labs and areas served by Hazardous Exhaust fans. See attached list.									
Service to be #1 Hazardous Exhaust #2 #2 #4 Description/Reason for Project: Down for annual maintenance on exhaust systems.									
Requester: Steve MacKay Date of Request: Apr 20, 2016									
Supervisi	ng Trad	esperson:		Unit:					
Trade Sup	ervisor	:		Unit:				Date:	
Contractor: Phone # Coordinator/Project Manager: Steve MacKay Phone # 88764 Date:									
Reviewed by Trade Supervisor(s)/Shop(s) Affected:									
Name: Signature/ Stamp:		WES Control REVIEWED By Wayne Drummond (ppdwad@uwo.ca) at 10:23 at		Signature Stamp:				Dat	e:
Name:	Name: Principal Occupants:								
Signature/ Stamp:			Name:			Ext.		Date:	
Name: Date:		Name:	Name:		Ext.		Date:		
				Name:			Ext.		Date:
Signature/ Stamp: Approval to Proceed: Date:									
Name: Signature/ Stamp:	Signature/								
Notes: Co	uld trigg	ger alarms at fume hoods	for low flow.						

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING DENTAL SCIENCE

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES	
110-001- 500		<mark>6000</mark>	Wall of roof K	W.R. Exhaust	Louvre above K	
-003-	4028 A&B	К	К	Room Exhaust	1 ½" acetone exhaust	
-005-	6000	6000	Wall of roof k	Mech. Rm. Ex.	Louvre Above K	
-006-	5006	K	K	Fume Cabinet		
-007-	5006	K	K	Fume Cabinet		
-008-	5005	K	K	Fume Cabinet		
-009-	5005	K	K	Fume Cabinet		
-012-	5000-I	K K	K	Room Exhaust	CAN NOT ACCESS ROOM	
-013-	5000-H *CHECK NOTE	<mark>K</mark> 	K	Room Exhaust	CAN NOT ACCESS ROOM	
-014-	4035A	K	K	Fume Cabinet	Radio Isotope – stack	
<mark>-016-</mark>	5000 A	<mark>6000</mark>	Wall of Roof K	Shower Exhaust	Louvre above K	
-023-	0025	K	K	Fume Cabinet		
-030-	0142X	<mark>K</mark>	K	Autoclave Ex.	still not in use – may 08 LOCKED OFF 2013	
-032-	1008B	К	K	Hood	Switch Rm. 1008D	
-033-	1008B	K	K	Hood		
-034-	1018	<mark>K</mark>	<mark>K</mark>	Dryer Ex.		
-055-	2019	К	K	Fume Cab	6 TH FLOOR PANEL ED1H #29&31	
-056-	3013B	K	K	Sterilizer Ex.		
- 058-	3023	<mark>K</mark>	<mark>K</mark>	Hood	See note 6	
-067-	5014	K	K	Solvent Room		
-068-	5001	K	K	Fume Cab		
-069-	5001	K	K	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS	
-083-	3031	K	K	Fume Cab	Radioisotope Unit	
-086	0015	L	L	Fume Cab	New in 2003	
-090-	4020,4021	6000	Wall of Roof K	Operating Rm. Ex.	Louvre above K	
-096-	4034	K	K	Fume Cab	Radio Isotope stack	
-097-	5004	K	K	Fume Cab	Radio Isotope stack	
-007-501	5000	K	K	1 Fume Cab 1		

				Fume Hood	
110-108- 507	3025	<mark>K</mark>	K	Room Exhaust	
110-108- 505	3013	<mark>6000</mark>	Wall of Roof K	ACVS Room Exhaust	Louver Above

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN